

VEHICLE INSPECTION REPORT

FP69ZBD

Vauxhall Vivaro 2900 1.5 100PS Edition

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	44124
Cap Code	VAVI15191DVDTM2 3 L

Details

Location	Doncaster	GVW	2830kg	CAP Clean	£6,650.00
Reg. date	31/12/2019	Colour	WHITE	CAP Average	£5,725.00
Year	2019	VIN	VXEVBVYHRKL7008600	CAP Below	£4,475.00
Mileage	61,203 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	06/07/2027	Gears	6

INTERMITTENT WARNING LIGHT TWIN SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF

OSR




Spare

Features

- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door nsf
Chipped
Multiple Chips

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Other
N/A
N/A

8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Wing osf
Chipped
Multiple Chips

10: Seat Base Cover osf
Torn
Over 3mm



11: Seat Base Cover nsf
Soiled
Heavy

12: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault