

VEHICLE INSPECTION REPORT

PE17HNG

Daf CF 440

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 01/03/2017

Year 2017

Mileage 1,300,941 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G148943

Body Style Tractor Unit

MOT Due 31/05/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

NON-RUNNER, CLUTCH ISSUES, WONT SELECT GEAR, WARNING LIGHTS ON DASH

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
Over 30mm



3: Unclassified
Major Parts Missing
Report Only



4: Wing osf
Poor Previous Repair
Rippled Over 30%



5: Carpets Front
Torn
Over 10mm



6: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		